



## Design of Conventional Permanent Magnet Synchronous Motor used in Electric Vehicle

EI KYAW AUNG NAY TUN<sup>1</sup>, THET TIN<sup>2</sup>

<sup>1</sup>Dept of Electrical Power Engineering, Mandalay Technological University, Mandalay, Myanmar, E-mail: eisanmgw@gmail.com.

<sup>2</sup>Dept of Electrical Power Engineering, Mandalay Technological University, Mandalay, Myanmar.

**Abstract:** Conventional permanent magnet synchronous motors are popularly used in electric vehicle application. This study addresses the theoretical design of a conventional permanent magnet synchronous motor (PMSM) for electric vehicles. The study applies to both surface mounted and inset magnet rotor configurations. Various losses estimations are embedded into the design procedures to ensure that the desired overall drive performance is achieved. Influences of parameters such as air gap size and magnet material on the performances are studied. Application of neodymium-iron-boron (Nd2Fe14B) and samarium cobalt (Sm2Co17) rare earth magnets results in high torque and power density, efficiency, and controllability, reliability, and ruggedness. Design of 47 kW PMSM with various magnets for electric car is presented.

**Keywords:** Electric car, Design theory, Nd2Fe14B, PMSM, Surface PM rotor.

### I. INTRODUCTION

An electric car is an alternative-design automobile that uses an electric motor to power the car, with the electricity being provided by a battery. In an electric vehicle the traditional gasoline or diesel engine and fuel tank is replaced with an electric motor, a battery pack and controller. The vehicle also has a controller that powers the electric motor uses rechargeable batteries as its energy source. The motor itself can be either AC or DC. The main advantage to electric vehicles is that the motor and battery configuration allows the vehicle to run more fuel-efficiently [1]. The permanent magnet synchronous motor (PMSM) is considered to be a better fit for electric cars because the PMSM offers some advantages as low rotor inertia, high efficiency, efficient heat dissipation structure, and reduced motor size. The elimination of brushes reduces noise and suppresses the need for brush maintenance is another big advantage.

### II. PRINCIPLE OF ELECTRIC CARS

Electric vehicles can be divided into three main types: hybrid electric vehicles (HEVs), pluggable hybrid electric vehicles (PHEVs) and full electric vehicles (FEVs/BEVs/EVs). Hybrid electric vehicles retain the internal combustion engine and drive, while also incorporating a small battery and electric drive motor. While the higher efficiency of the electric drive and the capacity for regenerative braking results in decreased fuel consumption, the vehicle cannot be powered by electricity alone and still relies on petrol or diesel. Full EVs are generally mechanically less complex than both internal combustion and hybrid vehicles, as shown in Fig.1. Consequently, the vehicle can be driven over short ranges where it only consumes

electricity from the battery. However, beyond a defined level of battery consumption the vehicle reverts back to using the internal combustion engine alongside the electric motor like a standard hybrid. Table I shows the description of components in Fig 1. By replacing the fuel tank with a high energy density battery and the internal combustion engine with an efficient electric motor, EVs are capable of achieving significant efficiency improvements and emission reductions. Their range, efficiency, cost and torque-speed characteristics are predominantly determined by their battery pack and electric motor(s).




Fig 1. Key Functional Components Typical to an EV [1].

**TABLE I: Description of Components in Figure-1**


Components	Description
Electric Motor	Permanent magnet synchronous motor powered by three-phase AC from the inverter that supplies
Li-ion Battery	High specific energy electrochemical supply for powering the vehicle during operation
Reduction Gear Inverter	Steps down motor speed and increase torque
HV Junction Box	Converts DC power from Li-ion battery to three-phase AC power for controlling the motor
Electric Compressor	Interfaces the Li-ion battery with high-voltage systems
PTC Heater	Compressor for cabin air conditioning
Charge Ports	Positive temperature coefficient heat source for the interior cabin
Charge port	Standard connection ports for interfacing with EVSE to recharge the battery
On-board Charger	Converts AC power supplied to the standard charge port into DC power for recharging the battery
DC/DC Converter	Steps down the HV Li-ion supply to recharge 12V VRLA battery
VRLA Battery	12V valve-regulated lead-acid battery that powers the low voltage systems; headlights, audio, display
HV Cables	High rated conductors for carrying DC current between battery and HV systems
Service Plug	Allows the HV systems to be manually disconnected from the battery
Power Supply Backup	Capacitor-based power system that supplies power to the brakes and emergency system if 12V battery fails

### III. PERMANENT MAGNET SYNCHRONOUS MOTOR

The PM Synchronous motor is a rotating electric machine where the stator is a classic three phase stator like that of an induction motor and the rotor has surface-mounted permanent magnets. In this respect, the PMSM is equivalent to an induction motor where the air gap magnetic field is produced by a permanent magnet. The use of a permanent magnet to generate a substantial air gap magnetic flux makes it possible to design highly efficient PM motors. A PMSM is driven by sine wave voltage coupled with the given rotor position. The generated stator flux together with the rotor flux, which is generated by a rotor magnet, defines the torque, and thus speeds, of the motor.

#### A. Stator Construction

The stator is the stationary part of the motor. The core of the stator is made up of several hundred thin laminations. Stator laminations are stacked together forming a hollow cylinder and coils of insulated wire are inserted into slot of the stator core. The basic concept of the motor operation is electromagnetism which is, each group of coils together with the steel it surrounds form an electromagnets. The stator winding are connected directly to the power circuit. Fig 2 below shows the stator case with the winding insulator.



**Fig.2. Stator Case with Winding.**

#### B. Stator Coil Arrangement

The windings are connected in wye. The two windings in each phase are wound in the same direction. At any instant in time, the magnetic field generated by one particular phase will depend on the current through that phase. Since the currents in the three windings are 120° out of phase, the magnetic fields produced will also be 120° out of phase. The three magnetic fields will combine to produce one field, which will act upon the rotor. In an AC induction motor, a magnetic field is induced in the rotor opposite in polarity of the magnetic field in the stator. Therefore, as the magnetic field rotates in the stator, the rotor also rotates to maintain its alignment with the stator's magnetic field. This motor used six winding for electrical configuration of stator winding, two for each of the three phases. The coils are wound around the soft iron core material of the stator. When current applied each winding become electromagnet with one winding is a north pole and the other is south pole, the polarities of the winding also reverse.

#### C. Winding Insulation

Insulation of the winding is one of the most critical parts in this design. When the insulation breaks down, the machine shorts out. The cost of repair machine with shorted insulation is expensive and sometimes impossible. The temperature of the winding should be limited to prevent the insulation from breaking down because of the overheating. This can be preventing by providing circulation of cool air over the windings. The continuous power supplied to the machine usually limited by the maximum temperature of winding. The increased in temperature usually degrades the insulation. Life of the machine is halved for a temperature rise of 10 percent above the rate temperature winding. In this motor prefer used type F insulation class. This type of insulator is the most commonly used for motor. The allowable temperature 105°C rise from ambient temperature 40°C.

#### D. Rotor Construction

The type of rotor used is permanent magnet type. With a permanent magnet mounted on a shaft can be substituted for brush-type shaft with slip ring of rotor. When stator winding

## Design of Conventional Permanent Magnet Synchronous Motor used in Electric Vehicle

are energized, a rotating magnet is established. The magnet has its own magnetic field that interacts with rotating magnetic field of the stator. The north pole of the rotating field attracts the south pole of the magnet, and the south pole of rotating magnetic field attracts the north pole of the magnet. As the magnetic field rotates, it pulls the magnet along. NdFeb rare earth magnet is the type of permanent magnet suitable used to produce strong magnetic field. Fig 3 shows the mounted magnet on the rotor shaft.



Fig.3. Mounted magnet on the rotor shaft.

### E. Rotor Configuration

Permanent magnet synchronous motors are usually built with one of the following rotor configurations.

- Classical (Merrill's rotor), with salient poles, laminated pole shoes and a cage winding,
- Interior-magnet rotor,
- Surface-magnet rotor,
- Inset-magnet rotor and,
- Rotor with buried magnets symmetrically distributed.

### F. Surface PM Rotor

The surface magnet motor can have magnets magnetized radially or sometimes circumferentially. An external high conductivity non-ferromagnetic cylinder is sometimes used. It protects the PMs against the demagnetizing action of armature reaction and centrifugal forces, provides an asynchronous starting torque, and acts as a damper as shown in Fig.4. If rare-earth PMs are used, the synchronous reactances in the d-and q-axis are practically the same.




Fig.4. Surface-magnet rotor.

## IV. DESIGN THEORY OF PMSM

Synchronous machines are designed to achieve the following information regarding its various parts supply.

- Main dimensions of stator frame,
- Complete details of the stator winding,
- Details Design of the PM rotor and
- Performance of the designed parts, in order to justify the design of the above parts.

Design of electrical machines mainly consists of obtaining the dimensions of the various parts of the machine to suit given specifications, using available material economically and then to furnish these data to the manufacture of the machine.

### A. Main Dimensions of Stator Frame

Internal diameter and gross length of the stator frame are its main dimensions. It is essential to develop an equation connecting the output of synchronous motor with its main dimensions in order to estimate the latter.

For the synchronous motor,

$$D_{in}^2 L_i = \frac{P_{out} \times \epsilon}{\sigma_p n_s} \quad (1)$$

$$\sigma_p = 0.5 \pi^2 k_{\omega 1} A_m B_{mg} \eta \cos \phi$$

Where,

$D_{in}$  — Internal diameter of stator, (cm)

$L_i$  — Gross length of stator, (cm)

$P_{out}$  — Designing power, (W)

$\sigma_p$  — Output coefficient

$\epsilon$  — Relative eccentricity

$N_s$  — Synchronous speed, (rev/s)

$k_{\omega 1}$  — Winding coefficient

$A_m$  — Specific electric loading, (A/m)

$B_{mg}$  — Air-gap magnetic flux density, (T)

$\eta$  — Efficiency

$\cos \phi$  — power factor

The size and cost of synchronous machine is decreased by choosing comparatively a higher value of air gap flux density. However, operating flux density in stator teeth and core increases, which results into higher iron losses. Thus reducing the efficiency and raising the temperature rise of the machine. With improvement in magnetic materials, it is possible to choose comparatively higher value of flux density in modern synchronous machines. Output equation clearly indicates that the size of the machine for the same output can be reduced by choosing higher value of specific electric loading, which amounts to decreased cost of the machine. Moreover, the leakage reactance and the armature reactance of synchronous machine are higher with large value of specific electric loading.

Internal diameter and gross length of the stator can be calculated from the product  $D2L$ . And a suitable relation is assumed between  $D$  and  $L$ . For round pole- The ratio of pole

arc to pole pitch may be assumed from 0.6 to 0.7 and pole arc may be taken equal to the axial length of the stator core. The length of air gap in synchronous machines is an important design parameter because its value greatly influences the performance of the machine. However, longer length of air gap will require increased values of field mmf making the machine costly.

**B. Stator Winding**

Slot pitch, which depends upon the number of slots, should have approximately the following values for different cases. For low voltages machine: Less than or equal to 3.5 cm. Normally, the number of poles is quite large in non-salient pole synchronous machine and the number of slots per pole per phase may be assumed from 1 to 3. Number of turns per phase can be calculated, using the emf equation of synchronous machines.

Total number of stator slots,  $S = mpq$   
 Where,  $m =$  number of stator slots per pole per phase  
 Conductors per slot,

$$N_{cs} = \frac{N_1}{\text{no : of conductor/ phase}} \tag{2}$$

Turns per phase,

$$N_1 = \frac{A_m p \tau_p}{3\sqrt{2} I_a} \tag{3}$$

The pole pitch,

$$\tau_p = \frac{\pi D_{lin}}{2p} \tag{4}$$

Where,  $\tau_p$  — pole pitch, m;  $y$  — number of slots per pole  
 Air gap flux per pole,

$$\phi_f = \frac{2}{\pi} \tau_p L_i B_{mg} l \tag{5}$$

Stator winding factor  $k_{\omega 1}$  may be assumed as per the winding details. For full pitch coils with infinitely distributed winding, stator winding factor, is  $k_{\omega 1}$  equal to 0.955. The number of turns should be an integer. Sectional area of the conductor for the stator winding can be calculated, based on the stator current per phase and operating current density for the stator winding.

Sectional area of conductor,

$$a_s = \frac{I_a}{J_s} \tag{6}$$

Current density,  $J_s$  should be assumed as per the cooling system used. Usual values for the current density in the stator winding can be assumed varying from 3 to 5 A per  $\text{mm}^2$ .

Width of the teeth,

$$b_t = \frac{\phi}{B_t \times L_i \times N_t} \tag{7}$$

Where,  $N_t$  — the number of teeth per pole arc

Flux core section,

$$\phi_c = \frac{1}{2} \phi_f \tag{8}$$

The outer diameter of the stator is calculated from:

$$D_{out} = D_{lin} + 2h_s + 2d_c \tag{9}$$

Mean length of stator turn,

$$l_{le} = 2.5\tau_p \tag{10}$$

$$l_{mt} = (2L + 2.5\tau_p + 0.05kV + 0.15) \tag{11}$$

Resistance of stator winding,

$$R_s = \frac{\rho l_{mt} N_1}{a_s} \tag{12}$$

Where,  $\rho$  — resistivity

$a_s$  — sectional area of stator conductor, [ $\text{mm}^2$ ]

**C. Rotor Magnet Dimension**

The volume of all PMs used in a motor  $V_M = 2ph_M w_M l_M$  depends on the quality of PM material (maximum energy). In above equation  $2p$  is the number of poles, and  $h_M, w_M,$  and  $l_M$  are the height, width and length of the PM, respectively. The output power of a PM synchronous motor is proportional to  $V_M$ . The maximum electromagnetic power developed by PM synchronous motor can be expressed as follows:

$$P_{max} = \frac{\pi^2 \xi f B_r H_c V_M}{2k_f k_{ad}(1 + \epsilon)} \tag{13}$$

Where,

$k_f$  — form factor of the rotor

$k_{ad}$  — d-axis armature reaction factor

$\xi$  — coefficient of utilization of the PM

$f$  — input frequency

$B_r$  — remanent magnetic flux density

$H_c$  — coercive force

**D. Efficiency of PMSM**

Copper Losses of Stator Winding,

$$P_{cu} = 3 I_a^2 R_s \tag{13}$$

Eddy current losses in the stator conductors,

Average loss factor,

$$K_{dsv} = 1 + (a h_c)^4 \frac{m^2}{9} \tag{14}$$

Eddy current Loss,

$$P_{eddy} = (K_{dsv} - 1) P_{cu} \tag{15}$$

Efficiency of the motor,

$$\eta = \frac{P_{out}}{P_{out} + \text{Total Losses}} \times 100\% \tag{16}$$

**V. DESIGN CALCULATION OF 47 KW PMSM**

In this paper, 47kW three-phase surface mounted PMSM is designed for EV. At the speed of PMSM range from 0 to 2000 rpm, the maximum torque is 180 Nm, but the EV PMSM is controlled by the number of poles of PMSM used in EV is calculated as follow,

$$\text{pole} = \frac{120 \times f}{n_s} = \frac{120 \times 50}{3000} = 2 \tag{17}$$

The input line to neutral voltage;

## Design of Conventional Permanent Magnet Synchronous Motor used in Electric Vehicle

$$V_{ph} = \frac{380}{\sqrt{3}} = 219.39V \quad (18)$$

The armature rated current;


$$I_a = \frac{P_{out}}{3V_1 \eta \cos\phi} \quad (19)$$

$$= \frac{47000}{3 \times 219.39 \times 0.94 \times 0.8} = 94.959A$$

Table II shows the detail designed data sheet for 47kW surface mounted magnet PMSM.

**TABLE II: Detail Designed Data Sheet for PMSM with Magnet NDFEB**

Specification	Symbol	Unit	Value
Full Load Output	$P_1$	kW	47
Line voltage	V	Volts	380
Phase	-	-	3
Frequency	f	Hz	50
Speed	n	r.p.m	3000
Internal diameter of stator	$D_{i,in}$	mm	140
Gross Length of stator	$L_i$	mm	210
Peripheral Speed	V	m/s	21.991
Flux per phase	$\phi_n$	Wb	$32 \times 10^{-2}$
Turns per phase	$N_1$	-	24
Number of slots	$N_s$	-	12
Conductor per slot	$N_{cs}$	-	12
Conductor c.s.a	$a_s$	mm <sup>2</sup>	27.3
Width of slot	$b_{cs}$	mm	18
Depth of slot	$h_s$	mm	68
Resistance of winding	$R_s$	$\Omega$	0.031
Leakage reactance	$X_l$	$\Omega$	0.124
Outer diameter of the stator	$D_{e,out}$	mm	414
Length of PM	$l_M$	mm	210
Height of PM	$h_M$	mm	15
Width of PM	$w_M$	mm	$4 \times 3 = 12$
Copper losses in stator winding	$P_{cu}$	W	838.62
Eddy current losses in conductors	$P_{eddy}$	W	126.538
Stray load losses	$P_s$	W	144.774
Total losses	$P_t$	W	1109
Rotor losses	-	-	-
Efficiency	$\eta$	%	98



**Fig.5. Efficiency of designed PMSM for Various Magnet.**

The Fig.5 shows the efficiency of the permanent magnet synchronous motor. The different type of permanent magnet materials such as  $Sm_2Co_3$ ,  $Sm_2Co_{17}$  and NdFeB are mounted on the rotor of PM. By changing the magnets, the efficiency of the PMSM is also changed.

## VI. CONCLUSIONS

The design considered in this paper is 47 kW, 3000 rpm surface mounted magnet PMSM. By changing the magnet material, not only the internal diameter of the stator and gross length of the stator but also the efficiency of the motor is also changed. As the magnetic flux density of the different magnet materials are not the same, the output coefficient is changed and other parameters concerned with the output coefficient are also changed. In this design, the NdFeB is chosen magnet to mount on the surface of the rotor because it has high efficiency compared with other magnet. The efficiency of the PMSM used NdFeB magnet is 98 per cent. The design of PMSM is suitable for EV. PMSM offers some advantages as low rotor inertia, high efficiency, efficient heat dissipation structure, and reduced motor size.

## VII. ACKNOWLEDGEMENT

First of all, the author would like to acknowledge the support and the encouragement of Prof. Dr. Myint Thein, Pro-rector, Mandalay Technological University. The author is deeply indebted to Dr. Khin Thuzar Soe, Associate Professor and Head of Department of Electrical Power Engineering, Mandalay Technological University, for her invaluable help and indispensable guidance. The author wishes to extend grateful thanks to her supervisor, U TheTin., Lecturer, Department of Electrical Power Engineering, Mandalay Technological University, for his supervision, critical reading of manuscript and tolerance helped in all the time of this research work. The author is also special thanks to all her teachers and friends who help in preparation of this paper. The author specially thanks to her family, especially her beloved parents, for their supports and encouragements to attain her destination without any trouble.

## VIII. REFERENCES

- [1] Anonymous, "Electric Vehicles: Charged with Potential", Royal academy of engineering, 2010.
- [2] Bhim Singh, B.P.Singh, S Dwivedi, "A State of Art on Different Configurations of Permanent Magnet Brushless Machine", 2002.
- [3] Jacek F. Gieras Mitchell Wing, "Permanent Magnet Motor Technology design and application", 2<sup>nd</sup>, Ed 2002.
- [4] Tayfun Gundugdu, "Design of Permanent Magnet Machines with Different Rotor Type", 2000.
- [5] Miss Sisuda Chaithongsuk, "Design and Construction of a Permanent Magnet Synchronous Motor", ISBN 974-190-887-3, 1989.